Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2168Work Order Type: WeatherizationAudit Name: 14014SO2168

CLIENT INFORMATION

Client Name: 14014SO2168 Address: , Unit 1396

Client ID: 14014SO2168 Columbia, TN 38401

Alt. Client ID: Maury

CLIENT CONTACT INFORMATION

14014SO2168 Applicant/Person of ✓

Record

<u>AGENCY INFORMATION</u>

Agency: South Central Human Resource Agency Agency Phone: (931) 433-7182

Address: 1437 Winchester Highway Fax: (931) 438-0074

Fayetteville, TN 37334 *Email Address:*

Agency Contact: Ford, Duane Work Phone:

Cell Phone: (615) 308-7878

Email Address: Fordd@hughes.net

Company Name & License Number:	

Contractor's Signature:

COMMENT

Older home in good cond., but leaky.

Client Name: 14014SO2168 Client ID: 14014SO2168 Alt. Client ID: Maury Work Order (Bid Form)

Work Order Name: 14014SO2168 Report Run On: 5/14/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 5

Measures

	Measure	1	Infilt	ration	Redctr	1					Compon	er	nts				Inspecte
C	Comment 1. Extensive air seal. 2. Clear caulk crown, walls, corners, casings, jambs, and window seats. 3. Air seal bedrm#2 closet. 4. Air seal bedrm#1 closet. 5. Repair ceiling bedrm#1 6. Re-glaze wood windows and caulk storms. 7. Foam all plumbing intrusions. 8. Seal corner of ceiling/stairs by bathroom door. 9. Seal DWH compartment. 10. Air seal old attic stairway door.																
											Estima	ted	d			Actual	
#	Material /	Lai	bor	Descr	iption / C	Comment	t	Units	Qt	y	Unit Cos	t	Total	(Qty	Unit Cos	t Total
1	Miscellar Supplies	ieo	ıs	Infiltra	ition Re	duction		Each	1								
2	Labor			Labor				Hour	8								
C	Other Detai	1															
] []
									Meas	sure	e Sub Tota	l:				Sub Total:	
	Field Note	es:															

	Replace Htg. System w/ B-v w/ Blower	enting ur	nit	Componen	ts Vente	d		Inspected	
Comment									
				Estimated	<u> </u>		Actual		
# Material / Labo	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Heating Equipment	Replace w/ B-venting unit w/ Blower	Each	1						
2 Labor	Labor	Each	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:									
	DWH Pipe Insulation			Componen	ts DWH			Inspected	
Comment				Estimated	1	Actual			
# Material / Labo	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	DHW Pipe Insulation	Each	1						
	All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.								
2 Labor	DHW Pipe Insulation	Each	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:									

Comment	place Back Door Unit, W	S, DS, Lo	Componen	ts Door		Inspected		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	Back Door Unit, WS, DS, Lock	Each	1					
2 Labor	Labor	Hour	1					
Other Detail] [
			Measu	re Sub Total:		•	Sub Total:	
	place Kitchen Door Unit, ck (3)	, 110, 20,		Componen				
				Estimateo	ı		Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Estimated	l Total	Qty	Actual Unit Cost	Total
	Description / Comment Replace Kitchen Door Unit, WS, DS, Lock	<i>Units</i> Each	Qty 1			Qty		
1 Doors	Replace Kitchen Door					Qty		
1 Doors	Replace Kitchen Door Unit, WS, DS, Lock	Each	1			Qty		
1 Doors 2 Labor	Replace Kitchen Door Unit, WS, DS, Lock	Each	1			Qty		
1 Doors 2 Labor	Replace Kitchen Door Unit, WS, DS, Lock	Each	1			Qty		
# Material / Labor 1 Doors 2 Labor Other Detail	Replace Kitchen Door Unit, WS, DS, Lock	Each Hour	1					

Page 4 of 5

Measure 7 Smoke/ CO2 Detector Combo					Componen		Inspected		
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke/CO2 Detector Combo	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail						1		
L									
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
			Work Or	der Gra	nd Total:		Gran	d Total:	

Page 5 of 5